


## IRON – IRON CARBON EQUILIBRIUM DIAGRAM

(Explain the Iron –iron carbide equilibrium diagram with the reactions taking place in it.)

- The iron-carbon phase diagram is used to understand the different phases of steel and cast iron. Both steel and cast iron are a mix of iron and carbon.
- This iron carbon phase diagram is plotted with the carbon concentrations by weight on the X-axis and the temperature scale on the Y-axis.
- The carbon is present as an interstitial impurity.



### Types of Ferrous Alloys on the Phase Diagram

- The weight percentage of carbon is from 0% to 6.67%.
- Up to 0.008% of Carbon, it is pure iron.
- It exists in the  $\alpha$ -ferrite form at room temperature.
- From 0.008% up to 2.14% carbon, it is called steel. Within this range, there are different grades of steel known as low carbon steel (or mild steel), medium carbon steel, and high carbon steel.
- As the carbon content increases beyond 2.14%, it is cast iron.

### Boundaries

- Boundaries are represented as lines in the diagram A<sub>1</sub>, A<sub>2</sub>, A<sub>3</sub>, A<sub>4</sub>, and ACM.

- A stands for 'arrest'.
- As the temperature of the metal increases or decreases, phase change occurs at these boundaries.
- Along these lines (A1, A2, A3, A4, and ACM) the heating results in a realignment of the structure into a different phase and thus, the temperature stops increasing until the phase has changed completely. This is known as thermal arrest as the temperature stays constant.

### **Eutectic Point**

- For the iron-carbon alloy diagram, the eutectic point is where the lines A1, A3 and ACM meet.
- At these points, liquid phase freezes into a mixture of two solid phases.
- The alloys formed at this point are known as eutectic alloys. On the left and right side of this point, alloys are known as hypoeutectic and hypereutectic alloys respectively.
- Hypo eutectoid steel – 0.008 to 0.8% of carbon
- Hypereutectoid steel – 0.8 to 2% of Carbon

### **Different Phases**

#### **$\alpha$ -ferrite ( $\alpha$ - iron)**

- Ferrite, also known as  $\alpha$ -ferrite ( $\alpha$ -Fe) or alpha iron, is **pure iron, with B.C.C crystal structure**.
- This phase is stable at room temperature and is magnetic below 768°C.
- It has a maximum carbon content of 0.022 % and it will transform to  $\gamma$ -austenite at 912°C.

#### **$\gamma$ -austenite ( $\gamma$ - iron)**

- This phase is a solid solution of carbon in FCC structure(Fe).
- On further heating, it is converted into BCC  $\delta$ -ferrite at 1395°C.
- This phase is non-magnetic.

#### **$\delta$ -ferrite**

- This phase has a B.C.C structure as that of  $\alpha$ -ferrite but exists only at high temperatures. The phase can be spotted at the top left corner in the graph.
- It has a melting point of 1538°C.
- It is ferromagnetic.

#### **Fe<sub>3</sub>C or Cementite**

- Cementite is a metastable phase of this alloy with a fixed composition of Fe<sub>3</sub>C.
- It decomposes extremely slowly at room temperature into Iron and carbon (graphite).

#### **Pearlite**

- Pearlite is **the eutectoid mixture of cementite and ferrite**.

#### **Ledeburite**


- Ledeburite is a mixture of 4.3% carbon in iron and is a eutectic mixture of austenite and cementite.

### Fe-C liquid solution


- 'L', is the liquid solution of carbon in iron.
- $\delta$ -ferrite melts at  $1538^{\circ}\text{C}$ , and this shows that melting temperature of iron decreases with increasing carbon content.

Reactions taking place is as follows,

➔ Peritectic reaction equation may be written as ( $2720^{\circ}\text{F}$ )



➔ eutectic reaction takes place at ( $2066^{\circ}\text{F}$ ) and its equation may be written as



➔ Eutectic point is at 4.3% carbon.

➔ Eutectoid reaction takes place at ( $1333^{\circ}\text{F}$ ) and its equation may be written as

