



SNS COLLEGE OF TECHNOLOGY

(An Autonomous Institution)



COIMBATORE-35

Accredited by NBA-AICTE and Accredited by NAAC – UGC with A+ Grade

Approved by AICTE, New Delhi & Affiliated to Anna University, Chennai

DEPARTMENT OF ELECTRICAL AND ELECTRONICS ENGINEERING

COURSE NAME: 23EET204/ ELECTRICAL MACHINES II

II YEAR / IV SEMESTER


Unit 2 – SYNCHRONOUS MOTOR

Topic 5: Power input and power developed equations





GUESS THE TOPIC NAME...





Synchronous Motor- phasor diagram

The phasor diagram of a synchronous motor is shown below. From the phasor diagram,

Let


V = Supply voltage / phase

I_a = Armature current / phase

R_a = Armature resistance / phase

α = Load angle

ϕ = Power factor angle





Synchronous Motor-Power developed



Input Power to Motor :

Motor input power / phase = $V I_a \cos \phi$

Total input power for 3- ϕ star-connected motor,

$$\begin{aligned} P &= \sqrt{3} V_L I_L \cos \phi \\ &= 3 V_{ph} I_{ph} \cos \phi \end{aligned}$$

Where

V_L and I_L are line values

V_{ph} and I_{ph} are phase values

Power Developed by Motor :

The mechanical power developed / phase,

P_m = Back emf * Armature current * Cosine of the angle
between E_b and I_a

$$= E_b I_a \cos (\alpha - \phi) \text{ for lagging p.f}$$

$$= E_b I_a \cos (\alpha + \phi) \text{ for leading p.f}$$



Synchronous Motor-Power developed

The copper loss in a synchronous motor takes place in the armature windings.

Therefore,

Armature copper loss / phase = $I_a^2 R_a$

Total copper loss = $3 I_a^2 R_a$

By subtracting the copper loss from the power input, we obtain the mechanical power developed by a synchronous motor as

$$P_m = P - P_{cu}$$

For three-phase,

$$P_m = \sqrt{3} I_L I_L \cos \phi - 3 I_a^2 R_a$$


Power Output of the Motor :

To obtain the power output we subtract the iron, friction, and excitation losses from the power developed.

Therefore,

Net output power, $P_{out} = P_m$ - iron, friction, and excitation losses.

The above two stages can be shown diagrammatically called as Power Flow Diagram of a Synchronous Motor



The power developed in a synchronous motor as follows.

Motor Input Power, P

1. Stator (Armature) copper loss P_{cu}
2. Mechanical power developed, P_m
 - a. Iron, friction, and excitation losses
 - b. Output power, P_{out}



Net Power Developed by a Synchronous Motor :

The expression for power developed by the synchronous motor in terms of α , θ , V , E_b , and Z_s are as follows :

Let

V = Supply voltage

E_b = Back emf / phase

α = Load angle

θ = Internal or Impedance angle = $\tan^{-1} (X_r / Z_s)$

I_a = Armature current / phase = E_r / Z_s

$Z_s = R_a + j X_s$ = Synchronous impedance

Mechanical power developed / phase

$$P_m = \frac{E_b V}{Z_s} \cos(\theta - \alpha) - \frac{E_b^2}{Z_s} \cos \theta$$



Net Power Developed by a Synchronous Motor :

The armature resistance is neglected

If R_a is neglected, then $Z_s \approx X_s$ and $\theta = 90^\circ$. substituting these values in the above equation

$$P_m = \frac{E_b V}{X_s} \cos(90 - \alpha) - \frac{E_b^2}{X_s} \cos 90^\circ$$

$$P_m = \frac{E_b V}{X_s} \sin \alpha$$



SUMMARY

Power input and power developed equations



KEEP
LEARNING..
Thank u

SEE YOU IN NEXT CLASS