



UNIT IV FERROUS AND NON FERROUS METALS

Cu alloys -Aluminium and Al -Cu -Precipitation Strengthening Treatment

Engineering Materials and Metallurgy


KARTHICK B

ASSISTANT PROFESSOR / MECHANICAL ENGG



Copper

- Mostly used in Non Ferrous Metals.
- Melting Point: 1083 deg C
- Very Good Corrosion Resistance





Properties

- High Electrical Conductivity
- High Thermal Conductivity
- Good Corrosion resistance
- Soft, Ductile and Malleable.
- Can be hot worked and cold worked but can't be welded





Applications

- ❑ Power cables
- ❑ Telephone cables
- ❑ Circuit boards
- ❑ Connectors
- ❑ Domestic water tanks and utensils
- ❑ For manufacturing brass and bronze





Copper Alloys



➤ Posses the following Characteristics

- High Electrical Conductivity
- High Thermal Conductivity
- Good Corrosion resistance
- Soft, Ductile and Malleable.
- Can be hot worked and cold worked but can't be welded



Cu Alloys

- Brass (Cu – Zn Alloys)
- Bronze (Cu-Tin Alloys)
- Gun Metal (Cu – Tin – Zn Alloys)
- Cupro Nickel (Cu – Ni Alloys)
 - Tellurium → Very Good Machinability
 - Cadmium → Increase in Strength and little loss in Conductivity
 - Beryllium or Cr → High Strength alloys.





Brass

- Upto 36 % Zn \rightarrow single phase solid solution \rightarrow α brass.
- More 36% Zn \rightarrow two phase solid solution \rightarrow α β brass.
- α brass \rightarrow soft, ductile and easily cooled worked.
- α β brass \rightarrow stronger than α brass





Characteristics

- Stronger than Cu
- Low Thermal and Electrical Conductivity than Cu.
- Cast into moulds and drawn into wires and rolled into sheets.
- 1 – 3% of Pb increases Machining Properties.
- Color: Reddish to White depend upon Zinc %.





Types of Brass

- Gliding Brass → Jewellery works.
- Cartridge Brass → Mfg Cartridge and shell
- Std Brass → Screws, rivets, tubes.
- Muntz Brass → Extruding Rods, tubes, heat exchanger plates.
- Naval Brass → Marine Structural uses.
- Admiralty Brass → Condensers, Pump impellers.





Bronze

- High strength with Good Corrosion than brass.
- Strength increase with Tin content.
- But Tin Content is below 12 % because it tends to be brittle.
- Rolled into wires, rods and sheets.





Types

- Bell Bronze → Making Bells
- Phosphor Bronze → Pumps parts, lining, springs.
- Si Bronze → Boiler parts, die cast parts, marine applications.
- Al Bronze → cams, rollers etc.
- Coinage bronze → making Cu coins
- Lead Bronze → Bearing alloys.





Gun Metal

- Zinc acts as deoxidized to increase fluidity.
- Lead is added to improve castability and machinability.
- Cheaper.





Types

- Admiralty Gun metal → Pumps, valves, castings.
- Leaded Gun Metal → Hydraulic gears, valves, etc.





Cupro Nickel

- Cu and Ni have unlimited Solubility.
- They are ductile and malleable.
- Better Corrosion resistance than any other in marine application.
- Hot or Cold worked.
- Shaped by forging, pressing, drawing, spinning.





Types

- Cupronickel → Salt water piping, condenser tubes and bullet envelope.
- Monel metal → pump fittings, sea water exposed parts, food handling plants.
- 'K' Monel → motor boat propeller shafts.





Aluminium Characteristics

- Light weight
- High Thermal and Electrical Conductivity
- Excellent Corrosion resistance
- Non Toxicity
- Low Sp.Gravity
- High Strength to Weight ratio.





Types



- **Heat Treatable Al Alloys:**

- Al – Cu Alloys

- Al – Cu – Ni Alloys

- Al – Mg – Si Alloys

- Al - Zn - Cu alloys

- Al – Li Alloys.

- **Non Heat Treatable Alloys:**

- Al – Mn Alloys

- Al – Mg Alloys

- Al – Si Alloys.

- Al – Cu alloys

- Duralumin

- Y Alloy.



Precipitation Strengthening

- Also Known as Age Hardening,
- It is used to improve the physical properties by solid state reaction.
- Most applicable for Al, Mg, Ni.
- Ex: Al - Cu, Cu - Be, Cu - Tin, Mg - Al.
- In this Process hardening takes place because the fine particles of the new phase are formed.




Process

- Its is explained with Al -4% Cu Alloy(Duralumin).
- Steps
 - Solution Treatment
 - Quenching
 - Ageing.



Al-Cu phase diagram showing three steps in Precipitation Hardening





Solution treatment

- Heating above the solvus temperature to obtain solid solution
- Hold until homogenous Solid solution
- This step dissolves the θ precipitate and reduces any segregation in original alloy.
- This treatment is done at the temperature range of 500°C and 548°C



Quenching

- After ST \rightarrow Rapid Quenched.
- On rapid cooling, there is no sufficient time for diffusion of Cu atoms to form precipitate particles.
- Hence supersaturated α_{ss} (containing excess Cu) is obtained at RT.
- Supersaturated α_{ss} is unstable.



Ageing

- α_{SS} is heated below the solvus temperature.
- At this ageing temp diffusion of α_{SS} may takes place and precipitate particles are formed.
- By holding at this same temperature for a sufficient time $\alpha + \text{CuAl}_2$ (θ) is formed.
- This CuAl_2 increases the hardness.



THANK YOU