



# SNS COLLEGE OF TECHNOLOGY

COIMBATORE-35



## DEPARTMENT OF MECHANICAL ENGINEERING

### UNIT -1

#### SIX SIGMA PRINCIPLES

## Six Sigma Statistics:

### 1. Basic Six Sigma Statistics:

These are the fundamental statistical tools used in Six Sigma to measure and analyze process performance:

*Mean ( $\mu$ ):*

- The **average** of a data set. It gives a central value and is used to understand the general trend of a process.

*Standard Deviation ( $\sigma$ ):*

- A measure of the **spread** or **dispersion** of data around the mean. In Six Sigma, we aim to reduce the standard deviation to achieve more consistent and predictable processes.

*Variance:*

- The square of the standard deviation. It is another measure of spread that indicates how much individual data points differ from the mean.

*Range:*

- The difference between the highest and lowest values in a dataset. It provides a simple, quick snapshot of data variability.

---

### 2. Defects and Defects Per Million Opportunities (DPMO):

Six Sigma is all about reducing defects. To measure defect levels and improvement, we use **DPMO**, which represents how many defects occur per million opportunities.

- **Formula for DPMO:**

$$\text{DPMO} = \left( \frac{\text{Defects}}{\text{Opportunities}} \times \text{Units} \right) \times 1,000,000$$

$$\text{DPMO} = \frac{\text{Defects} \times \text{Units}}{\text{Opportunities}} \times 1,000,000$$

- **Example:** If 2 defects occur in 500 products, with 3 opportunities per product, the DPMO would be:

$$\text{DPMO} = \left( \frac{2}{500} \times 3 \right) \times 1,000,000 = 1,333$$

$$\text{DPMO} = \frac{(500 \times 3) \times 2}{1,000,000} = 1,333$$

The goal is to reduce DPMO to as close to zero as possible.

---

### 3. Sigma Levels:

The **sigma level** measures process performance. It reflects how well a process is performing in terms of defects. The higher the sigma level, the fewer defects there are.

- **Six Sigma** represents a process that is **99.99966% defect-free** (3.4 defects per million opportunities).
- **A 1-sigma process** has a much higher defect rate (about 690,000 defects per million opportunities).

The standard sigma scale is as follows:

- **1 Sigma** = 690,000 defects per million
- **2 Sigma** = 308,000 defects per million
- **3 Sigma** = 66,800 defects per million
- **4 Sigma** = 6,210 defects per million
- **5 Sigma** = 233 defects per million
- **6 Sigma** = 3.4 defects per million

**Six Sigma** level is the ultimate goal, where the process is **almost perfect**, with minimal defects.

---

### 4. Control Charts:

Control charts are used to monitor process variation over time, helping identify trends, shifts, or abnormal variations. Common types of control charts include:

- **X-bar Chart:** Measures the average of a sample over time.
- **R-chart:** Measures the range (variation) within a sample.
- **P-chart:** Used for **proportional data** (defect rate) to monitor the percentage of defective items.
- **C-chart:** Used for **count data** (defect counts per unit) to monitor the number of defects.

Control charts help ensure the process is stable and predictable, which is a key requirement for Six Sigma.

---

## 5. Process Capability (Cp, Cpk):

Process capability measures how well a process can produce output within specification limits. It tells you whether the process is capable of meeting customer requirements and specifications.

- **Cp (Process Capability Index):**

$$Cp = \frac{USL - LSL}{6\sigma}$$

Where:

- **USL** = Upper Specification Limit
- **LSL** = Lower Specification Limit
- **σ** = Standard deviation

**Cp** measures how much room is available between the specification limits relative to the process spread. A Cp value of 1 means the process is just capable of meeting the specifications.

- **Cpk (Process Capability Index with Centering):**

$$Cpk = \min\left(\frac{USL - \mu}{3\sigma}, \frac{\mu - LSL}{3\sigma}\right)$$

Where:

- **μ** = Mean of the process

**Cpk** accounts for the process's centering (whether the mean is at the center of the specification limits). A Cpk value greater than 1.33 is typically considered acceptable in Six Sigma.

---

## 6. Z-scores:

A **Z-score** indicates how many standard deviations a data point is from the mean. In Six Sigma, Z-scores are used to measure how far a process is from perfection (i.e., the target).

- **Formula for Z-score:**  $Z = \frac{X - \mu}{\sigma}$  Where:
  - **X** = Data point
  - **μ** = Mean
  - **σ** = Standard deviation

For example, a Z-score of **6** corresponds to a **Six Sigma** level (very few defects).

---

## 7. Hypothesis Testing:

Six Sigma also uses **hypothesis testing** to make data-driven decisions. It helps test assumptions about a population based on sample data. Common hypothesis tests include:

- **t-test:** Used to compare the means of two groups.
- **ANOVA (Analysis of Variance):** Used to compare means across more than two groups.
- **Chi-square test:** Used for categorical data to determine if there is a significant association between variables.

These statistical tests allow Six Sigma practitioners to make decisions about process improvements and whether changes result in meaningful improvements.

---

## 8. Regression Analysis:

**Regression analysis** helps identify relationships between variables and predict future performance. It's especially useful in analyzing how different process inputs (independent variables) affect outputs (dependent variables).

- **Simple Linear Regression:** Models the relationship between two variables (one independent and one dependent).
  - **Multiple Regression:** Models the relationship between multiple independent variables and one dependent variable.
- 

## 9. Pareto Analysis:

Pareto analysis, based on the **80/20 rule**, helps prioritize which issues to address first by focusing on the most significant problems. This can be done by plotting a **Pareto chart**, where data is displayed in descending order of frequency, helping you identify which issues contribute most to the overall problem.